
PARTS FOR THE “LITTLE DUKE” SHOWING FACTORY PART NUMBERS







SAMPLE

Important: When ordering repair parts, be sure to give the complete number of the part as shown on the illustrations above. Unless otherwise indicated, the prefix “E.B.” should be included on each part number. “C.S.P.” means that the part consists of several individual parts made up into one unit.

Always give us the serial number of the machine for which the parts are to be used This will prevent confusion and assure proper handling of your order.

JENNINGS “LITTLE DUKE” Manufactured by **O.D. JENNINGS & COMPANY** 4309-39 W. Lake St., Chicago, USA